



Service Bulletin

Bulletin No.: 21-NA-251

Date: November, 2021

INFORMATION

Subject: Information on Appearance Concern with Driver Outside Rearview Mirror Dimming

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Corvette	2020	2022	—	—	All	All

Involved Region or Country	North America, Europe, Middle East, Japan, Australia/New Zealand
Condition	 <p style="text-align: right; font-size: small;">5918432</p> <p>Some customers may comment that their driver outside rearview mirror has numerous lines in it and it looks dim all the time. The electrical device may cause higher voltage to the mirror.</p>
Cause	This condition may be caused by the installation of an aftermarket radar detector jumper harness that powers a radar detector.
Correction	<p>Note: If this Condition is found, it may be a customer pay repair and NOT a Warrantable repair.</p> <p>The technician should inspect for a jumper harness added to the mirror's X1 connector. The connector located behind the front cover of the inside rearview mirror.</p> <p>Authorization for disconnecting the jumper harness, and/or replacement of a damaged outside rearview mirror, must be obtained from the customer.</p>

Version	1
Modified	Released November 05, 2021

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



**WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION**